

From: ["Wallingford, Jonni B." <wallingfordjb@cdmsmith.com>](mailto:Wallingford, Jonni B. <wallingfordjb@cdmsmith.com>)
To: ["Sheldrake, Sean" <sheldrake.sean@epa.gov>](mailto:Sheldrake, Sean <sheldrake.sean@epa.gov>)
["Zhen, Davis" <Zhen.Davis@epa.gov>](mailto:Zhen, Davis <Zhen.Davis@epa.gov>)
CC: younghs@cdmsmith.com
["Scott Coffey" <coffeyse@cdmsmith.com>](mailto:Scott Coffey <coffeyse@cdmsmith.com>)
Date: 8/1/2018 4:31:28 PM
Subject: NAPL Sheen Sediment Coring Sample
Attachments: [Snapchat-775050704.jpg](#)
[Snapchat-1000810512.jpg](#)
[Snapchat-1388227324.jpg](#)

Good afternoon,

At site SC-S806 (RM 5.6), three subsurface sediment samples cored. All 3 samples were observed to have sheen and/or NAPL present. The two cores that were not retained were discarded in 5 gallon buckets to be disposed of (photo 2 & 3). 1 core with NAPL present will be retained (photo 1).

Jonni

Photo 1: NAPL product on core tube

Photo 2: disposing contaminated core

Photo 3: NAPL sheen present in core attempt #2

Get Outlook for Android<<https://aka.ms/ghei36>>